## Aeronautical Systems Center Air Force Plant 6 Marietta, Georgia



## Administrative Record Index Part 2 of 5

## THIS INDEX INCLUDES ALL DOCUMENTS

03020 THROUGH 03059

## **Prepared by:**

U.S. Department of the Air Force
Aeronautical Systems Center
Acquisition Environmental, Safety and Health Division (ASC/ENVR)
Wright-Patterson AFB, Ohio

**UPDATED September 2006** 

ASC/ENVR Wright-Patterson AFB, Ohio 1-800-982-7248, extension 53417

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
3020	3.04	Supplemental RCRA Facility Investigation (SRFI) Work Plan For the Position 65 C-5 Wash Rack Ponds Area; Air Force Plant 6,	Black & Veatch Waste Science, Inc.	50	3/28/1994
		Marietta, Georgia			
	3.04	Work Plan For the Hydrogeologic Investigation and Groundwater	B & V Waste Science and	113	7/31/1993
		Modeling Retention Basin 2, Building B-58, and Building B-76;	Technology Corp.		
		Air Force Plant 6, Marietta, Georgia			
	3.04	Addendum No.1, Work Plan to conduct Supplemental RCRA	International Technology	381	2/4/1997
		Facility Investigation at Sites B-4, B-10, and B-90	Corporation		
3023	3.02	Semiannual Corrective Action Report- Supplement; January-	Parsons Engineering	446	9/30/1997
	3.02	June 1997; Appendices A, B, and C; Groundwater Compliance	Science, Inc.	770	3/30/1337
		Monitoring & Reporting for U.S. Air Force Plant No.6, Marietta,			
		Georgia			
3024	3.02	Semiannual Corrective Action Report; January-June 1997; B-10	Parsons Engineering	264	9/30/1997
0021	0.02	Building Area; Groundwater Compliance Monitoring & Reporting	Science, Inc.	201	0,00,1001
		for U.S. Air Force Plant No. 6, Marietta, Georgia			
3025	3.05	RCRA Facility Investigation Report for Off-Site Contamination	Parsons Engineering	666	9/30/1997
3025	3.03	NONA Facility investigation report to on-one contamination	Science, Inc.	000	9/30/1997
3026	3.02	Semiannual Corrective Action Report, January-June 1997;	Parsons Engineering	251	9/30/1997
		B-90 Building Area; Groundwater Compliance Monitoring & Reporting for U.S. Air Force Plant No.6, Marietta, Georgia	Science, Inc.		
3027	3.06	Letter from Lockheed Martin to Georgia EPD, Subject: RCRA Facility Investigation Report for Off-Site Contamination	Lockheed Martin	2	9/19/1997
		Facility investigation Report for Oil-Site Contamination	Aeronautical Systems		
3028	3.06	Letter from Lockheed Martin to Georgia EPD, Subject: Submittal	Lockheed Martin	3	10/9/1996
		of Revised Pages( for Revised RFI Workplan), October 9, 1996	Aeronautical Systems		
3029	3.06	Letter from Lockheed Martin to Georgia EPD, Subject: Comments	Lockheed Martin	12	9/23/1997
0020	0.00	on Draft Hazardous Waste Facility Permit No.HW-034(D) EPA	Aeronautical Systems	12	0/20/1007
		ID. GA 8570024606			
3030	3.01	Site-Specific Field Sampling Plan, Investigation of Groundwater	Lockheed Martin	86	11/30/1997
3030	3.01	Treatment Technologies for Position 65 C-5 Wash Rack Area	Aeronautical Systems	00	11/30/1991
3031	3.02	Semi-Annual Corrective Action Report; July-December 1997; B-10 Building Area	Parsons Engineering Science, Inc.	271	5/31/1998
		b-10 building Area	Science, inc.		
3032	3.04	Naval Air Station Fuel Farm RCRA Facilities Investigation Work	IT Corporation	78	6/30/1998
		Plan			
3033	3.04	Addendum No.2 Work Plan to Conduct Supplemental RCRA	Lockheed Martin	39	5/31/1998
		Facility Investigation at Sites B-4, B-10,and B-90; DRAFT	Aeronautical Systems		
3034	3.05	Corrective Action Plan and Baseline Risk Assessment for IRP	Parsons Engineering	288	6/30/1999
3034	3.03	Site #10, JP-5 Leak Area	Science, Inc.	200	0/30/1999
3035	3.05	Aquifer Test Report Site B-4 Interim Corrective Measures at Sites B-4, B-10, and B-90	Lockheed Martin Aeronautical Systems	814	10/17/1997
		Sites 6-4, 6-10, and 6-90	Aeronautical Systems		
3036	3.05	Final Summary of Findings Document Phase II Supplemental	Lockheed Martin	306	4/19/1999
		RCRA Facilities Investigation at B-4, B-10,and B-90; Volume	Aeronautical Systems		
		1 of 2			
3037	3.05	Final Summary of Findings Document Phase II Supplemental	Lockheed Martin	359	4/19/1999
		RCRA Facilities Investigation at B-4, B-10, and B-90	Aeronautical Systems		
3038	3.05	Baseline Risk Assessment Buildings B-30 and B-78 Areas	ape Environmental Managemer	212	5/31/1999
5050	5.05	Describe Mak Assessment Dunungs D-30 and D-10 Aleas	Inc.		0/0///1999
3039	3.05	Semiannual Corrective Action Report; July-December 1997;	Parsons Engineering	239	5/31/1998
		B-90 Building Area	Science, Inc.		
3040	3.05	Semi-annual Corrective Action Report-Supplement; July-	Parsons Engineering	1102	5/31/1998
·		December 1997;Appendices A, B, and C	Science, Inc.		

DOCNO	CATEGORY	TITLE	AUTHOR	PAGE	DATE
3041	3.05	Semi-Annual Corrective Action Report; January-June 1998; B-90 Building Area; Groundwater Complaince Monitoring and Reporting	Parsons Engineering Science, Inc.	320	9/30/1998
3042	3.05	Semi-annual Corrective Action Report; January-June 1998; B-10 Building Area	Parsons Engineering Science, Inc.	312	9/30/1998
3043	3.05	Semi-Annual Corrective Action Report-Supplement; January- June 1998; Appendices A, B, and C	Parsons Engineering Science, Inc.	917	9/30/1998
3044	3.05	Semiannual Corrective Action Report January - June 1999, B-90 Building Area	Parsons Engineering Science, Inc	297	9/30/1999
3045	3.05	Semiannual Corrective Action Report January - June 1999, B-10 Building Area	Parsons Engineering Science, Inc	327	9/30/1999
3046	3.05	Semiannual Corrective Action Report January - June 1999 Appendices A, B, and C	Parsons Engineering Science, Inc	868	9/30/1999
3047	3.06	Letter from Parsons Engineering Science, Inc., 24 Jan 00, Subject: September 1999, Semiannual Corrective Action Reports for AFP 6, Marrietta, GA	Parsons Engineering Science, Inc	1	1/24/2000
3048	3.05	Semiannual Corrective Action Report Jul-Dec 99 B-90 Building Area Groundwater Compliance Monitoring & Reporting for AFP 6	Air Force Center for Environmental Excellence	307	6/30/2000
3049	3.05	Semiannual Corrective Action Report Jul-Dec 00, B-10 Building Area Groundwater Compliance Monitoring and Reporting for AFP 6	Air Force Center for Environmental Excellence	332	6/30/2000
3050	3.05	Semiannual Corrective Action Report Jul-Dec 00, Appendices A, B, and C, Groundwater Compliance Monitoring & Reporting for US AFP No. 6	Air Force Center for Environmental Excellence	1113	6/30/2000
3051	3.04	RCRA Facility Investigation Work Plan B-99 Area	tlanta Environmental Manageme	173	5/31/2001
3052	3.05	Semiannual Corrective Action Report July-December 2000, B-10 Building Area, Groundwater Compliance Monitoring	CH2MHill	240	04/01/01
3053	3.05	Semiannual Corrective Action Report July-December 2000, B-90 Building Area, Groundwater Compliance Monitoring	CH2MHill	240	04/01/01
3054	3.04	Semiannual Corrective Action Report July-December 2000, Groundwater Compliance Monitoring Appendices A, B, and C	CH2MHill	1343	Apr-01
3055	3.04	Data Consolidation Summary Report US AFP 6	IT Corp	162	2/1/2003
3056	3.04	Bedrock Investigation Work Plan Addendum to SRFI Phase III Site Characterization Investigations at AFP 6	CH2M Hill	48	7/1/2003
3057	3.05	Final Work Plan and Appendices SRFI Phase III Site Characterization Investigations for the B-4, B-10, and B-90 Building Areas	CH2MHill	685	11/1/2001
3058	3.05	Report of Findings RCRA Facility Investigation Aviation Fuel Farm	IT Corp	762	10/1/2002
3059	3.05	Draft Revised Final Summary of Findings Document Phase II Supplemental RCRA Facility Investigation at the B-4, B-10, and B-90 Areas, US AFP 6 Volume 1 of 2	IT Corp	280	2/0/2005